Inspection report

FICTIONAL SAMPLE - NOT CLIENT EVIDENCE

Identification	Value
Report ID	QC-20261101-DEMO-001
Client / supplier	FICTIONAL CLIENT / FICTIONAL WORKSHOP
Site / inspection date	Imaginary site, no real address / 2026-11-01 (fictional)
Service / revision	Live half-day (fictional) / DEMO v1
Reviewer / specification	No real inspector / DEMO-SPEC-01

Executive summary

Fictional lot: 200 units / 20 cartons; 20 units sampled from 5 cartons.

3 unique defective units: 0 Critical, 1 Major and 2 Minor occurrences.

Top issues: misaligned lid (1 unit); cosmetic scratches (2 units).

Conditional: request correction and verification before shipment.

Illustrative customer plan only. No real inspection or evidence exists.

Method

Customer-confirmed sampling plan DEMO-PLAN-01: 20 units from cartons C01, C05, C09, C13, C17; 4 units per carton. Illustrative systematic selection, not a statistically validated random sample. Fictional client criteria: 0 critical; any major requires correction and verification; minor issues reviewed before shipment.

inspected on a sampling basis — not a 100% inspection. No ISO/AQL compliance or certification is claimed. No unverified standard table is used. Sample findings do not establish a whole-lot defect rate.

Method and findings

Illustrative session: 14:00-17:00 Asia/Shanghai (UTC+08:00), 2026-11-01; 180 minutes. Fictional participants: buyer and inspector. No interruptions in this invented scenario. No actual permission, session, tools or measurements exist.

Checklist: v2.0. Safety scope: non-destructive basic observations only; no lab, chemical, electrical-safety or certification results.

Section	Findings	Evidence index
Quantity	20 cartons declared; fictional count 20. Four units per selected carton.	P01 / 00:05
Workmanship	U02 and U03: cosmetic scratches; two minor occurrences.	P02 / 00:35
Function	U01 lid does not align; one major occurrence.	P03 / 00:50
Packaging & Labels	Illustrative checked labels match DEMO-SPEC-01. No legal compliance conclusion.	P04 / 01:10
Consistency with specs	Lid fit differs from fictional reference; unmeasured dimensions not checked.	P03 / 00:50

Defect list

ID	Grade	Description / units	Qty	Photos
D01	Major	Misaligned lid / U01	1	P03
D02	Minor	Cosmetic scratches / U02, U03	2	P02

Counts are defect occurrences; unique affected units must be deduplicated. Here the fictional counts are 1 + 2 = 3, on three separate units.

Photos and evidence index

All entries below are fictional index examples. No photographs, recording, links or client evidence exist. Offsets are invented and are not proof of a visit.

Photo ID	Caption	Source	Video
P01	Carton count / C01	NO REAL FILE	00:05
P02	Scratches / U02, U03	NO REAL FILE	00:35
P03	Lid fit / U01	NO REAL FILE	00:50
P04	Label / C05	NO REAL FILE	01:10

The four fictional rows show index structure only, not the promised delivery photo count. A real live half-day order requires 30+ timestamped photos; a full-day order requires 60+. Never substitute invented media.

Delivery and retention

Fictional example only: report, replay, photos and defect links do not exist; no cloud retention is claimed. Real orders must record controlled links and a retention date at least 90 days out.

Disclaimer

This report records what was observed on site on the inspection date, based on sampling. It is not a product certification, lab test result, or a guarantee of the supplier or of unsampled units. The shipping recommendation is advisory; the final decision remains yours.

FICTIONAL DEMONSTRATION ONLY. This document records no real on-site observation and must not support a shipping, payment, certification or customer-testimonial claim.